

CERTIFICATE

- Name of the Building** : Carmel School
Pranthya Village, Moodabidri
Dakshina Kannada.
- Village/Taluk/District** : Pranthya Village/ Dakshina Kannada.
- No of Floors** : Ground, First, Second and Third Floor.

This is to certify that the Carmel School Building situated at R.S. No. 150/2, Pranthya Village is structurally stable and under serviceable condition. The components of the Buildings are sound and structurally strong.

Hence, I certify that I have inspected the premises and examined the various components of the existing building. I am of the opinion that all the existing conditions of the building is structurally sound and in serviceable condition.

Place: Mangaluru

Date : 28-05-2022


28/05/2022
ALEN BAPPA ENGINEER